


横断地盤線
測点3+00.000



▽
- <CrossSect name="0+60.00" sta="60.">
- <CrossSectSurf name="現況地形16" desc="">
 <PntList2D>-50. 28.110735518624 -47.684639010696
 28.127101798054 -42.58650655155
 28.114593675949 -42.176661757561
 28.11434048762 -37.464320289079
 28.123835307426 -19.845822833073
 28.939096590291 -18.732663054614 29.
 -18.698169140295 29.000513097121
 -18.571407666329 29.001235212446
 -18.298991000904 29.003776956062
 -18.16154982891 29.004472334304
 -18.004208885844 29.00631607445
 -17.573503941727 29.006645963442
 -17.248371356135 29.007402428901
 -16.610015367192 29.010020223569
 -16.040901478049 29.017712037873
 -15.192003329913 29.026002859616
 -11.478067255274 29.24999329451
 ① -5.479367543354 29.582498408086
 ② -1.55233649787 29.999999999998
 ③ 0.000000000024 30.255997899867
 ④ 2.877263366989 30.730491271835
 ⑤ 4.277502538801 31.000000000004
 ⑥ 6.077411885707 31.505856722251
 7.98852340122 31.971995514342
 8.078733999276 31.994293595975
 8.110679098425 31.999999999999

【読取り結果】
【チェックポイント】

項番	項目	CL離れ・標高	チェック結果	備考
1	構成点①～⑨	上記の通り	一致 不一致	

